

REPORT NO.

CD NO.

INFORMATION REPORT

CLASSIFICATION SECRET

COUNTRY

East Germany

DATE DISTR.

28 May 1954

SUBJECT

Repair of Submarine

NO. OF PAGES

1

PLACE ACQUIRED

635434

NO. OF ENCLS.
(ENTER BELOW)

DATE OF INFO.

SUPPLEMENT TO
REPORT NO.

25X1

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES. WITHIN THE MEANING OF TITLE 16, SECTIONS 702 AND 706, OF THE U. S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE REPRODUCTION OF THIS FORD IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

25X1

On 12 March 1954, when source was at the Volkswerft Stralsund (the Stralsund nationalized shipyard), he found out that the submarine concerned was to be entirely reconditioned. She was to get four torpedo tubes. Her electrical equipment and the storage battery were entirely unserviceable. The new gear required for her reconditioning was being manufactured at the VEB Elektro-Aparate Werke (Electrical Apparatus Works) in Berlin-Treptow. The old periscopes also were entirely unusable, and new ones were to be manufactured by the Carl Zeiss firm in Jena. Her engines were to be replaced by engines from stocks left by the former German Navy and, of course, needed thorough overhaul prior to being installed.

25X1

Comment. The funds needed for the reconditioning of the submarine will approximate the cost of a new submarine.

CLASSIFICATION SECRET

25X1

STATE	NAVY	NSRB	DISTRIBUTION						
ARMY	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>						